



STANDARD BOOSTER MODEL 3200-90C/91C
(C-FLANGE UNIT)

The following list of parts, headed by the booster model number and series, are the recommended spare parts for a normal overhaul. This list includes all bearings, seals, and miscellaneous lock and screws that are not normally reusable after disassembly.

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.

REPAIR KIT 32184

<u>Item Number</u>	<u>Description</u>	<u>Part Number</u>	<u>Quantity</u>
0	Loctite Threadlocker	93347	1
9	Ball Bearing	8499-D	2
10	Ball Bearing	28680	2
13	Lip Seal	32157	1
16	Timing Gear Shim Kit	28267	1
24	Gear Key	8600	2
29	Cap Screw	90293-100	4
30	Cap Screw	90214-1	16
51	Lab Seal	28622	4
54	Mechanical Seal	32018	4
66	Cap Screw	90359-150	2
76	Mechanical Seal	30226	1
92	O-Ring	29361-144	1
118	Shim	32171	5

The following part(s) are listed for reference only and are not a part of the repair kit:

8	Gear Assembly	29603	1
---	---------------	-------	---

5/26/04 kw

~Deleted item #49 90200 brass safety wire - replaced by 93347 loctite threadlocker

~Added item #66 90359-150 cap screw